

NEW CONSTRUCTION INSPECTION FORM

| ITEMS INSPECTED | DRAW 1 | DRAW 2 | DRAW 3 | DRAW 4 | DRAW 5 |
|--------------------------------|-----------|-----------|-----------|----------|-----------|
| Excavation & permits | 50.00% | 50.00% | | | |
| Footings | 100.00% | | | | |
| Foundation | 100.00% | | | | |
| Floor joists | 100.00% | | | | |
| Sub-floor | | 100.00% | | | |
| Framing | | 40.00% | 60.00% | | |
| Exterior sheatthing | | | 100.00% | | |
| trusses | | | 100.00% | | |
| Roofing | | | 100.00% | | |
| Windows | | | 100.00% | | |
| Siding | | | 100.00% | | |
| Sofit Enclosed | none | | | | |
| Rough plumbing | 100.00% | | | | |
| Rough heat/ductwork | none | | | | |
| Tub & shower | | | | 100.00% | |
| Finish plumbing | | | | | |
| Rough electrical | | 100.00% | | | |
| Finish electical | | | | 30.00% | 70.00% |
| Cess pool & septic system | 100.00% | | | | |
| Drive way excavation | | 100.00% | | | |
| Dirve way poured | | 100.00% | | | |
| Catchment tank | | | 50.00% | 50.00% | |
| Insulation | | | | 100.00% | |
| Drywall or plastic | | | | 100.00% | |
| Pump system | | | | 100.00% | |
| Cabinets & vanities | | | | | 100.00% |
| Interior painting | | | | 100.00% | |
| Outside painting | | | 100.00% | | |
| Light fixtures | | | | | 100.00% |
| ceramic tile/flooring | | | | | 100.00% |
| Counter top | | | | | 100.00% |
| Interior & exterior doors hung | | | | 100.00% | |
| Appliances | | | | | 100.00% |
| Decks/porch | | 30.00% | 70.00% | | |
| Gutter | | | | 100.00% | |
| Landscapping/sprinkers | | | | | 100.00% |
| | | | | | |
| INSPECTED BY: | | | | | |
| Chris Rither | | | | | |
| Date completed | 1/25/2004 | 2/27/2004 | 4/15/2004 | 5/1/2004 | 5/27/2005 |
| | | | | | |

NEW CONSTRUCTION INSPECTION FORM

| | | | | | |
|-----------------------|--|--|--|--|--|
| Comments/suggestions | | | | | |
| | | | | | |
| | | | | | |
| Photographs Included: | | | | | |